

Blue Ink - PCO  
Red Ink - Ith - Acoustic

DATE	Location	Type of Houses Construction	Observer
8/14/01 8/17/01	K. L. Malaysia	Bungalow --- 1 Flag --- 4  All walls are concrete + wooden frame + wood attic + wood paracet ceiling + wooden Door	TR. Not much detection Monotone / yes
8/20/01 8/21/01	Penang Malaysia	Flag - 5  All wall - concrete + wooden frame + wooden Door Ceiling - concrete	All these houses has been treated with insecticide Lofax Dying own insecticide Above ground dirt were in place. Therefore termite has been somewhat deterred and delayed. As a result they did not get together in big groups & would be less active.  In some cases due to cost there is also due to the high humidity. Put Acoustic and pick up their activities some

Above 10 houses: PCO already ~~saw~~ knows the  
presence of termite.  
Therefore I am not  
going to include these  
houses into my study

Date	Location	Type of House Construction	Observation
9/17/01	Portola	US type construction about 2000 ft <sup>2</sup> Took 20 min to locate termites & about 1 hr to check the whole house. 2 stone <sup>suspected spots</sup> <sup>confirmed spots</sup> PCO: miss <sup>2 or 3</sup> <sup>miss</sup> <sup>miss</sup> WE: found <sup>1</sup> <sup>1</sup> <sup>1</sup>	Termite detected! Took only 20 mins. IR also detected other nest marks which was confirmed by dry wall and PCO call me to check the spot to tell me the termite but I said I can find it
9/17/01	Oxford	US type construction about 2000 ft <sup>2</sup> Took 1 hr to inspect the whole house. 2 stone <sup>suspected spots</sup> <sup>confirmed spots</sup> PCO: NO <sup>no signs</sup> WE: YES <sup>1</sup> <sup>1</sup>	Termite detected in the garage area, about the door But also detected many inspection spots but couldn't confirm NO termite.
9/28/01	Tupelo (fillmore)	US type <sup>suspected spots</sup> <sup>confirmed spots</sup> one story <sup>no signs</sup> about 1700 ft <sup>2</sup> PCO: NO (twice) WE: YES <sup>found termite in 2 minutes</sup>	"Termite reinfestation" This house was treated one year ago with Sentron & spray the suspected spots with permethrin 75 but the house 2 months later owner called twice said she can hear termite activities, so I did not find any there. He called me to check. It took 2 minutes to locate termite in that room (just check that room)
10/4/01	Oxford	US type one story about 1750 ft <sup>2</sup>	"Termite detected" found termite in the garage door weather trim 1 hr to check the whole house

DATE	LOCATION	Type of House Construction	Observations
8/22/01	Singapore	2 story Bungalow - ① - Yes 2 stories Semi detach - ② - Yes	IR - (Yes) (quite obvious)
8/27/01	WE: Yes	Concrete wall Wood Roof + Clay Roof Ceiling Wood products	Acoustic - yes (very loud)
8/27/01	Went near home: IR suspected spot: 2 IR Confirmed spot: 1 Bungalow (Ant's mound) Found termite on the stairs. Case 3rd step Paying Ant house (88 Jth parking) IR suspected spots: 2 IR Confirmed spots: 2 app pcc superior spot: 3 app pcc conf spot: 0 Oxford	My mother house has monthly inspection found termite at lower sect. of door frame. Pay ant (light hill crast) IR suspected spot: 1 IR confirmed spot: 1	None of the house has been treated in the passed 26 months
8/27/01	ISOM Building	Big old Historical building. A big house about 4500 ft <sup>2</sup> too about 1 1/2 hr to check	NO Termite
	WE: NO PCC: NO (1st floor in Termites)	US Type Construction (2 stories)	The house has termite control and is questionable to 1 inch deep drillers. The termite control no \$5000/yr they spray with PCC 75 or fl
8/27/01	Oxford Paying Ant's suspected spot 0 confirmed spot 0 WE: NO PCC: NO app pcc superior spot: 0 app pcc conf spot: 0	New building about 5 years old 3700 ft <sup>2</sup> to check for ant mound took about 1 1/2 hr to inspect	what cream spray outside No termite.
		app pcc superior spot: 0 app pcc conf spot: 0	

1/15/92	Rolling Hill (Oxford)	Craig Hickey Suspected sp: 3 confir sp: 0 # of sp: pco suspect # of sp: pco confir 0	Many nice tanner in the ceiling but No tants both IR & A canth.
2/9	pro NO We: Yes suspected sp: 3 confir sp: 2 # of sp: pco suspect 0 # of sp: pco confir 0	Sarah Davis house after I found termite kitchen Sarah Davis called up the pest control to come & replace the board House was under renovation in Sept when the card board was removed located in 2200 yr suspected sp: 1 confir sp: 1 # of suspension set by pco # of sp: pco confir 0 Ted Smith	Three spots of wood area acoustic sensor picking up in 2 close locati: in the kitchen wall House has Sarthcon in place since last year IR did pick up wet spot and acoustic sensor pick up termites sand in the kitchen & living room wall low range 3000 + ft <sup>2</sup> house has a few suspension spot # of pco suspect 0 # of pco confir 0
4/24	pro: NO We: Yes	in the master bed room wall suspected spots: 3 confir spots: 1 James Cameron	IR did not detect any termites - perhaps termite activity is low
5/24	Lakeview garden pro NO We: Yes	Suspected spots: 0 confir spots: 1 (by Antares) # of sp: pco suspect 0 # of sp: pco confir 0	
5/6	Near Square pro NO We: Yes	Eric Fairbanks Small cabin suspected spots: 3 confir spots: 2 # of sp: pco suspect: 6 # of sp: pco confir: 1	IR - see spots Acoustic - Yes

## Report

PCO  
Suspected  
Porter

HomeSoft  
Confirm  
positive

2002

8/2

Kenny's Home

Tara Estate

We: No

PCO: No

spots suspected: 3  
confirm spots: 0  
PCO suspected spot: 0  
PCO Conf spot: 0

8/19

we: yes (Porter ID)  
PCO: No

Karen Muller  
Bruce Miller

Suspected spots: 4  
Confirm spots:  
PCO suspected spot: 0  
# spots PCO Conf: 0

8/20

we: yes (Porter ID)  
PCO: old boy. yes

Andy H. Perkins  
Hwy 7 North  
Suspected spots: 8  
Confirm spots: 4  
PCO suspected spots: 6  
# spots PCO confirm: 2

8/20

we: No  
PCO: No

Jim McClure  
Camp Ground Road  
Suspected spots: 2  
Confirm spots: 0

PCO suspected spots: 0  
# spots PCO Conf: 0

Total # of Suspected spots: 141  
Total # of Confirmed spots: 50

## Actual Confirmation

PCO  
suspected

HomeSoft  
suspected spots

# of spots  
confirm

Total: 44

by us: 30

by PCO: 12

House in Coastal Pk.

PCO suspected	HomeSoft confirmed
49	6

2002

2002  
3/68NE of Tupelo  
30 miles

We: Yes

in kitchen - but  
not in the living roomPCO: Yes on  
old damage in living room  
not on life tent  
But no more life tent  
in the living room

3/28

Potter-C

We: NO

PCO: NO (100%)

IR found some  
Suspicious spots but  
Averaging in the room

# of suspicious spots: 1

# of conf. by PCO: 0 (old exit in yard)

IR found some  
Suspicious spots

# of suspicious spots: 1

# of conf. by PCO: 0 (old exit part)

3/28

Betula. Potluc  
S New Alber

We: NO

PCO: NO

Not coming M.O. 20

Total: 40

We: 28

PCO: 12

Tent. The chens - through  
sheet rock in the living  
room.House was treated with  
Serticon for more than  
half a yearBut no more life tent  
in living roomI found tent in the living  
portion of the wall in the  
kitchen - outer wall.

Suspected spots: 4

Conf. : 1

# of suspicious spots: 1

# of conf. by PCO: 0 (old exit in yard)

House was baited with  
Serticon for a year2 year. but spring  
time (early march) there  
was a swamp of tent  
But I did not find any  
tent suspected spots: 3

Conf. : 0

House was baited  
Serticon for a year  
but has a swamp in  
early march. But I

did not find any

suspected spots: 4

Conf. : 0

part

part

Location

Rolling Hill  
(Oxford)

PCO No  
We No

PCO No

We Yes

suspected spots: 3

Confir spots: 2

# of spots PCO suspected: 0

# of spots PCO Confir: 0

Wood land hill

original

10:30 - 11:00

PCO: Yes

We: Yes

PCO: ND

We: Yes

Lake wa.  
garden

PCO No

We Yes

Near Square

PCO No

We Yes

Coalg Hickory

Suspected spots: 3

Confir spots: 0

# of spots PCO suspected: 0

# of spots PCO Confir: 0

Sarah Davis house

also 2 found items

Kitchen Sarah Davis

called up the pest control

to come & replace

the bait

House was under renovation

in Sept when the card box

was removed

located in

suspected spots: 1

Confir spots: 1

# of suspected spots by PCO: 4

# of spots PCO Confir: 0

ted Smith

in the master

bed room wall

suspected spots: 3

Confir spots: 1

Janet Ramsted

suspected spots: 0

Confir spots: 1 (by Abner)

# of spots PCO suspected: 0

# of spots Confir: 0

Eric Fairmark's

Small cabin

suspected spots: 3

Confir spots: 2

# of spots PCO suspected: 6

# of spots Confir: 1

Many nice turner

in the ceiling but

No turner both IR

& a window

Three spots of wood

area acoustic sensor

pickup in 2 close locati

in the room wall

House has Sathcen in

place since last year

term sign at the exact

Apr. but no life turner spotted

IR did pick up

wet spot and

acoustic sensor pickup

turner seen in the

kitchen & living room

wall down area

3000 + ft known

has a few Super spot

PCO suspected: 0

PCO Confir: 0

IR did not detect any

acoustic - perhaps turner

around the

exterior wall

seeing

Acoustic - Yes

Date	Location	Type of Build	Observations
11/23/01	Bay St. Louis John PCO: NO WE: NO	Concrete build (John) $\approx 1300$ ft <sup>2</sup> suspected spots: 1 actually confirm spots: 0 21 pco suspected spots: 0 2 spots pco conf: 0	Some termite mud tubes on outside wall & No termite signs in
11/24	Ricky cabin between Bay St Louis & New Orleans WE: Yes PCO: <del>Yes</del> (for good pco)	Wooden cabin in & out $\approx 2000$ ft <sup>2</sup> equipped with every thing suspected spots: 6 confirm spots: 2 2 pco suspected spots: 2 1 of pco confirm: 1	only good termite 1) or two old unused crusack pole & water 2) or two new crusack pole that supporting the house. Small mud tubes Formosan termite
11/26	Chuck cabin next to Ricky cabin WE: Yes PCO: NO	Very old wooden cabin $\approx 1200$ ft <sup>2</sup> suspected spots: 7 confirm spots: 3 2 of pco suspected spots 2 of pco confirm spots: 0	many termite on the outside under supports and found some IR sign on the wall & floor & ceiling
11/15	Near Royal Oak 50% NO 100% in the with 50% YES with the same PCO: NO	Jeff Hollarn Brick house $\approx 1700$ ft <sup>2</sup> suspected spots: 3 confirm spots: 0	Some Termite IR spots near the fire place in but no termite Acoustic No visual sign 2 pco suspected spots: 1 2 confirm: 0



Location	Type of Building	Observations
1/23 Pass Christian (Mason) <sup>①</sup> <del>add</del> PCO: ? Yes (many) <sup>100%</sup> We: Yes <sup>100%</sup>	Constructed Old Wooden house 1800 ft <sup>2</sup> wooden wall in the whole house.	many termites in the attic were found (Hot) suspect sp: 7 conf: sp: 3 # of <del>sp</del> PCO suspect sp: 3 # of sp: conf: 0
Mason <sup>②</sup> <del>new</del> <del>house</del> PCO: No We: NO " House was sprayed all around each year " the replaced wall was also heavily sprayed	wooden frame, brick outside ~ 2000 ft <sup>2</sup> Suspected sp: 1 conf: sp: 0 # of sp: PCO suspect sp: 0 # of sp: PCO conf: 0	House is under a very good PCO Contractor care, they pump the concrete slab whenever the find small cracks. PCO spray the whole outer wall soil. The <sup>North</sup> garage wall was found to be badly infested 6 months ago but was replaced with half concrete & half 2' x 4" wall. & the <sup>inner</sup> wall was sprayed with
2/23 Bay St. Louis (Besse) <sup>①</sup> PCO: NO (definitely) We: Yes	Wooden wall & wooden siding ~ 3400 ft <sup>2</sup> old house but well maintained Suspected sp: 2 conf: sp: 2	House has no termite treatment # of PCO suspect sp: 0 # of sp: PCO conf: 0
2/23 Michael Bay St. Louis PCO: NO (Probably) We: Yes	Very old suspected sp: 2 wooden house ~ 1800 ft <sup>2</sup> # of PCO suspect sp: 0 # of sp: PCO conf: 0	How much work had to be done for <sup>wood</sup> <sup>to be</sup> <sup>done</sup> concrete support found some termite food in the concrete support

Date	Location	Type of build Construction	Observation
11/12/01	Oxford Rare species ibn	Wood + Brick 2800 sq ft	IR: NO Acoustic: NO
	PCO: NO We: NO	Centric on the have more than a year ago suspected sp: 0 conf sp: 0 # of suspected sp: 0 # of sp: pco conf: 0	House has not been put in 1 year + ago but 3 month ago found owna found termites to of termites outside house.
12/1/01	Oxford Diana West	Wood + Brick 1800 sq ft	IR: few sp Acoustic: (1) down corner + term sand (2) some sand in the main bed room for door
	We: Yes PCO: No (No sound off)	House was bought 3 mo ago suspected sp: 4 conf sp: 1 # of pco suspected sp: 0 # of sp: pco conf: 0	
11/13/01	Oxford Bob Hill	Wood & Brick House very close to wooded area I expect to see termites but suspected sp: 5 conf sp: 1 # of pco suspected sp: 1 # of sp: pco conf: 0	Rm Temp was 70°C IR didn't detect found a few signs the second floor by but Acoustic Confirmed was a small found a evidence in the garage wall the wall that they the garage (good sand) Term: Yes
	We: Yes PCO: NO (probably No)		

Location	Type of build	Observation
Bay St. Ln Mac's Cabin WE: Yes PCO: 80% No	Construction wooden House old ~ 100yrs	<p>superficial spots: 2 confirm spots: 1</p> <p># of PCO Superficial spots: 2 # of PCO confirm: 1 <sup>only by dry wood</sup></p> <p>? : Termites 60% yes</p>
New orlean Mac's home PCO: No WE: Yes 80%	<p>superficial spots: 3 confirm spots: 1 (dry wood with a corner screw)</p> <p># of PCO Superficial spots: 3 # of PCO confirm: 1</p> <p>TR: Some hot spot between children room &amp; external wall</p>	<p>Fire ant detected by</p> <p>active 2/1/02</p>
Tupelo Lake front Sub division PCO: No WE: No	<p>superficial spots: 3 confirm spots: 0</p> <p>Construction 2nd &amp; 3rd floor 2000 yrs</p>	<p># of PCO Superficial spots: 1 # of PCO confirm: 0</p> <p>(No termites detected)</p> <p>The home owner found termites few weeks ago &amp; PCO treated the house 3 day before we inspected the house</p>

<p>Bernard Jansen old house PCO: Yes Pest Control checked 10/4/2001 WE: Yes</p>	<p>2100 sq ft 1 bed room oak &amp; birch Construction type</p> <p>superficial spots: 5 confirm spots: 1</p> <p># of PCO Superficial spots: 1 TR: +++ many small signs in master bath, Daytime</p> <p># of PCO confirm: 0 <sup>change</sup></p>	<p>PCO Inspected on 10/4/2001</p> <p>I certified "No termites"</p> <p>but we found Termites in master bath &amp; daughter's closet (close to on place)</p> <p>Chisel (Total: 3) 4 locations</p>
---------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

probably no - if yes, has to be due to the old damage

They probably say in the master bath instead of in the daughter's closet

Date	Location	Type of building Construction	Observations
12/28/01	Bay St. house Chuck Brotz Home PCO or Owner: NO WE: Yes # of suspected spots: 3 # of spot PCO conf: 0	Suspected spot: 3 Carpenter spots: 1 old wooden house treated 3 years ago (many ants tenting) Owner put down bait (bought from window store) around the house 0.8 hr	Very well defined we found <sup>5000</sup> termite in the master bed room wall (2 across) saw a carpenter from the outside of the house IR: +++ Yes = termite
12/21/01	Bay St. house Corker's house WE: NO PCO: NO	0.8 hr suspected spot: 1 3800 ft <sup>2</sup> 2 carpenter spots Suspected with 8' concrete pole of 100 suspected spots: 0 # of spots PCO confirm: 0	No signs of termite
10/17/01	Bay St. house Rich's Mother WE: Yes PCO: Yes	1000 ft <sup>2</sup> old wooden house 0.7 hr Suspected spots: 8 Carpenter spots: 4 # of PCO suspected spots: 0 # of spot PCO confirm: 0	IR: +++ many many termites on the ceiling + wall Acoustic = carpenter +++ many termites in house
10/28/01	Bay St. house Joe Dea WE: 60% yes PCO: Yes	0.6 hr old wooden house Some suspected spots	Suspected spot: 4 Carpenter spots: 2 # of PCO suspected spots: 0 # of spot PCO confirm: 0

LOCATION	Type of Building Construction	Observation
8/10 Bay St Louis (Mississippi)	wooden wall + shed brick. Common mid South construction	found termites in the outside wall wood piling with acoustic sensor. IR did not pick up any <del>sub</del> subterranean signs at all.
Ridley's Home	2 wood frame	
We: Yes Pro: No (50% yes) for 6 good pro	Concrete slab Suspected sp: 3 Conf: sp: 1 1 house # of pcc suspect sp: 1 # of sp pcc conf: 1 (50%)	Yes (out side) with Acoustic sensor IR: found no termite signs

8/10 Bay St Louis Fritz Rogay Home	wooden wall, floor wooden ceiling conventional foundation with supporting posts under cross space	Some suspension signs out of the door old. Some damage in the pole but no termite signs
We: NO 80% Pro: Yes (75%) Suspected sp: 2 Conf: sp: 0	A very very fine house (contemporary houses)	?
# of pcc suspect sp: 4 # of sp pcc conf: 0	11:15 - 12:00 pm	IR: found 5 - 6 termite signs

8/10 Bay St Louis C. B. Taylor	wooden wall, floor conventional foundation	inside temp was the same as outside. Before IR did not work too well But found termites on the inside wall and with Acoustic sensor
We: Yes Pro: No (50% yes)	Suspected sp: 4 Conf: sp: 2 (acoustic) # of pcc suspect sp: 2 # of sp pcc conf: 1 (50%) 12:20 - 13:00	Yes

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☒ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☒ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:**

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**